

Securing Hazardous Energy (Delimber)



Before the operator leaves the operator's work station, procedures must be implemented to prevent the release of stored energy, accidental start up, or movement of the machine. 437-007-0725(1)

Grapples, delimber masts, feller buncher attachments, forks and other similar devices must be stable and not pose a hazard to personnel while maintenance or repair activities are performed. 437-007-0725(8)